






STEPS TO SUCCESSFULLY PROCEED IN THE DIGITAL TRANSFORMATION JOURNEY



LEVEL 0



Awareness: perception of value in process data



LEVEL 1




01

Mapping of elements present in the process



LEVEL 2



02

Study to define the parameters to be measured



LEVEL 3



03

Installation of new sensors and system integration of the existing one



LEVEL 4



04

**Installation IoT gateway
and edge computing**



LEVEL 5



05

Connection to the IoT platform



IoT Readiness Level



Swipe

LEVEL 6




06

Integration with data feed software (scada, mes, weather, etc)



LEVEL 7



07

**Data analysis with
traditional statistical
tools and first insights**




IoT Readiness Level



Swipe

LEVEL 8



08

Data analysis with AI & ML and actionable data feedback to the field



IoT Readiness Level



Swipe

LEVEL 9



09

**Measurement of benefits
and maintenance of
maximum performance**



